
# ATTACHMENT F.


# - INTERNAL PHOTOS -

SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 1/29

## (Internal Photo)






SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 2/29





Report No.: HCT-R07-032 3/29




TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 4/29




TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr


Report No.: HCT-R07-032 5/29







Report No.: HCT-R07-032 6/29







Report No.: HCT-R07-032 7/29






Report No.: HCT-R07-032 8/29






Report No.: HCT-R07-032 9/29






Report No.: HCT-R07-032 10/29


### (AMC-100 Sam)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 11/29






Report No.: HCT-R07-032 12/29




#### HYUNDAI CALIBRATION & CERTIFICATION TECHNOLOGIES CO., LTD.

SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032






Report No.: HCT-R07-032 14/29

## (BLD-200A)




## (BLD-200A 02)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 15/29


## (DTL-100A Top)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr


Report No.: HCT-R07-032 16/29





Report No.: HCT-R07-032 17/29


### (DTL-100A LED)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 18/29


### (DTL-100A)



#### HYUNDAI CALIBRATION & CERTIFICATION TECHNOLOGIES CO., LTD.

SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr


Report No.: HCT-R07-032 19/29






Report No.: HCT-R07-032 20/29


## (EMZ-100A Bottom)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 21/29





22/29 Report No.: HCT-R07-032



### HYUNDAI CALIBRATION & CERTIFICATION TECHNOLOGIES CO., LTD.

SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr


Report No.: HCT-R07-032 23/29


## (PSU-150 Top)




SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr

Report No.: HCT-R07-032 24/29






Report No.: HCT-R07-032 25/29



Report No.: HCT-R07-032 26/29


## (PSU-150 Bottom)



SAN 136-1, AMI-RI, BUBAL-EUP, ICHEON-SI, KYOUNGKI-DO, 467-701, KOREA TEL:+82 31 639 8517 FAX:+82 31 639 8525 www.hct.co.kr


Report No.: HCT-R07-032 27/29





Report No.: HCT-R07-032 28/29





Report No.: HCT-R07-032 29/29