




## ATTACHMENT F.

- INTERNAL PHOTOS -

Report No.: HCT-R07-042 1/13




(ALC-100 Top)



Report No.: HCT-R07-042 2/13



## (ALC-100 Bottom)



Report No.: HCT-R07-042 3/13






Report No.: HCT-R07-042 4/13







Report No.: HCT-R07-042 5/13




(AMC-100 CPU)



Report No.: HCT-R07-042 6/13




(AMC-100 Ext)



Report No.: HCT-R07-042 7/13




(AMC-100 Flash)



Report No.: HCT-R07-042 8/13




(AMC-100 Main Top)



Report No.: HCT-R07-042 9/13




## (AMC-100 Main Bottom)



Report No.: HCT-R07-042 10/13






Report No.: HCT-R07-042 11/13




## (SCS36-12BAT TOP)



12/13





Report No.: HCT-R07-042 13/13