




ATTACHMENT F.

- INTERNAL PHOTOS -

Report No.: HCT-R07-036 1/13




(ALC-100 Top)



Report No.: HCT-R07-036 2/13



(ALC-100 Bottom)



Report No.: HCT-R07-036 3/13






Report No.: HCT-R07-036 4/13







Report No.: HCT-R07-036 5/13




(AMC-100 CPU)



Report No.: HCT-R07-036 6/13




(AMC-100 Ext)



Report No.: HCT-R07-036 7/13




(AMC-100 Flash)



Report No.: HCT-R07-036 8/13




(AMC-100 Main Top)



Report No.: HCT-R07-036 9/13




(AMC-100 Main Bottom)



Report No.: HCT-R07-036 10/13




(AMC-100 Sam)



Report No.: HCT-R07-036 11/13




(SCS36-12BAT TOP)



Report No.: HCT-R07-036 12/13





Report No.: HCT-R07-036 13/13