Helen Zhao

Subject: FW: Firelinx, Inc., FCC ID: VAT-FLNXRF1, Assessment NO.: AN07T6826, Notice#1











S145FL-4-AH-2450 S.PDF

Installation Manual.pdf

Users Manual.pdf Antenna Spec.pdf

From: September Radecki

Sent: Monday, May 21, 2007 5:30 PM

To: Helen Zhao

Subject: FW: Firelinx, Inc., FCC ID: VAT-FLNXRF1, Assessment NO.:

AN07T6826, Notice#1

Hi Helen,

Here are the answers to your questions.

Question #1: The user manual and OEM installation manual are exactly the same, please explain what is the reason to submit both documents. <CCS Answer:> Please note that these 2 documents have been revised and are not identical now. There are additional sections in the User Manual related to software operation of the module, protocol, etc. Updated manuals are attached here. The reason for having the hardware information in both manuals is that currently we will only be using these modules in our own products, hence the User Manual will be used by our engineering staff in the design of new products based on these modules. This means that they need to know the proper means of locating and mounting these modules on any new host boards developed, in addition to the details of how to actually communicate with the modules.

Question #2: The user manual does not contain regulatory statements, such as 15.105(b), 15.21, and 15.247(i) non-colocation statements. Please update the user manual.

<CCS Answer:> Please see updated manual, attached.

Question #3: The user manual lists 5 antennas that will be authorized to use with the module. But the antenna specs provided in the filing do not include Nearson S145XX, but include Pulse antenna W1030, W1031, E1034, which are not even on the list. Please provide antenna spec of Nearson S145XX, please remove W1030, W1031, E1034 from Pulse antenna spec. <CCS Answer:> Attached is the Antenna Spec. for the Nearson S1045XX, and the Revised Antenna Spec removing antennas.

Thank you.

Best regards, September