Project Number: 09CA32261 File Number TC8314 Page 1 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

Annex 1. Measurement Plots

A1. Measurement result - Plot no. 1 Sub-clause : § 2.1046, § 24.232 - RF Power Output Measurement method : Conducted measurement at antenna connector port : UP Link - Lowest channel = 1851.25 MHz Measured channel : Max. Power output with modulated RF-carrier Operating condition 🔆 Agilent R Т Ref 21.86 dBm Atten 10 dB #Avg Log 10 dB/ Offst 31.2 dB PAvg W1 S2 Center 1.851 250 GHz #Res BW 30 kHz Span 3 MHz #VBW 1 kHz Sweep 246.8 ms (601 pts) **Channel Power Power Spectral Density** 24.22 dBm /1.2500 MHz -36.75 dBm/Hz

Project Number: 09CA32261 File Number TC8314 Page 2 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 2

Sub-clause : § 2.1046, § 24.232 - RF Power Output

Measurement method : Conducted measurement at antenna connector port

Measured channel : UP Link - Mid channel = 1887.5 MHz
Operating condition : Max. Power output with modulated RF-carrier



Channel Power

24.12 dBm /1.2500 MHz


Power Spectral Density


-36.84 dBm/Hz

Project Number: 09CA32261 File Number TC8314 Page 3 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result – Plot no. 3





Channel Power


24.13 dBm /1.2500 MHz

Power Spectral Density

-36.84 dBm/Hz


09CA32261 File Number TC8314 Project Number: Page 4 of 66

CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 5 of 66

CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 6 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 7 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 7

Sub-clause : § 2.1049 - Occupied Bandwidth

Measurement method : Conducted measurement at antenna connector port

Measured channel : Up Link - Lowest channel = 1851.25 MHz

Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 8 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 8

Sub-clause : § 2.1049 - Occupied Bandwidth

Measurement method : Conducted measurement at antenna connector port

Measured channel : Up Link - Mid channel = 1887.5 MHz
Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 9 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 9

Sub-clause : § 2.1049 - Occupied Bandwidth

Measurement method : Conducted measurement at antenna connector port


Measured channel : Up Link - Highest channel = 1913.75 MHz

Operating condition : Max. Power output with modulated RF-carrier




09CA32261 File Number TC8314 Project Number: Page 10 of 66

CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 11 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 12 of 66

CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 13 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 14 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 14



Measurement method : Conducted measurement at antenna connector port


Measured channel : Up Link - Lowest channel = 1851.25 MHz
Operating condition : Max. Power output with modulated RF-carrier



09CA32261 File Number TC8314 Project Number: Page 15 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 15



Measurement method : Conducted measurement at antenna connector port Measured channel : Up Link - Lowest channel = 1851.25 MHz

: Max. Power output with modulated RF-carrier Operating condition



09CA32261 File Number TC8314 Project Number: Page 16 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 16

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

: Conducted measurement at antenna connector port Measurement method

Measured channel : Up Link - Mid channel = 1887.5 MHz

Operating condition




Project Number: 09CA32261 File Number TC8314 Page 17 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

Center 5.750 GHz

#Res BW 1 MHz

A1. Measurement result - Plot no. 17




#VBW 3 MHz

Span 8.5 GHz

Sweep 14.2 ms (601 pts)


Project Number: 09CA32261 File Number TC8314 Page 18 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 19 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 20 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 21 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 22 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 23 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 24 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




File Number 09CA32261 TC8314 Project Number: Page 25 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 26 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 27 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 28 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 29 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 30 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 31 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 32 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




09CA32261 File Number TC8314 Project Number: Page 33 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 34 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 35 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



09CA32261 File Number TC8314 Project Number: Page 36 of 66


CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.



09CA32261 File Number TC8314 Project Number: Page 37 of 66

CDMA RF Repeater Model Number: Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 37



Project Number: 09CA32261 File Number TC8314 Page 38 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 38



Project Number: 09CA32261 File Number TC8314 Page 39 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 39

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block A:Lower Band edge

Measured channel : Up Link – Lowest channel = 1851.25 MHz(ch 25)
Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 40 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 40

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block A: Higher Band edge

Measured channel : Up Link – Highest channel = 1864.75 MHz (ch 275)

Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 41 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 41

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block D : Lower Band edge

Measured channel : Up Link – Lowest channel = 1866.25 MHz (ch 325)


Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 42 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 42



Measurement method : Block D: Higher Band edge

Measured channel : Up Link – Highest channel = 1868.75 MHz (ch 375)
Operating condition : Max. Power output with modulated RF-carrier



09CA32261 File Number TC8314 Project Number: Page 43 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 43




: Block B: Lower Band edge Measurement method

: Up Link – Lowest channel = 1871.25 MHz (ch 425) Measured channel Operating condition



Project Number: 09CA32261 File Number TC8314 Page 44 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 45 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 45

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block E: Lower Band edge

Measured channel : Up Link – Lowest channel = 1886.25 MHz (ch 725)

Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 46 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 46

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block E: Higher Band edge

Measured channel : Up Link – Highest channel = 1888.75 MHz
Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 47 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 47

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block F:Lower Band edge


Measured channel : Up Link – Lowest channel = 1891.25 MHz (ch 825)

Operating condition : Max. Power output with modulated RF-carrier




Project Number: 09CA32261 File Number TC8314 Page 48 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 49 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



Project Number: 09CA32261 File Number TC8314 Page 50 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 50

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block C: Higher Band edge

Measured channel : Up Link – Highest channel = 1908.75 MHz (ch 1175)

Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 51 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 51

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block G: Lower Band edge


Measured channel : Up Link – Lowest channel = 1911.25 MHz (ch 1225)

Operating condition : Max. Power output with modulated RF-carrier




Project Number: 09CA32261 File Number TC8314 Page 52 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



File Number 09CA32261 TC8314 Project Number: Page 53 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.




Project Number: 09CA32261 File Number TC8314 Page 54 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 54

£(f): f>50k Swp

Center 1.945 000 GHz



Span 5 MHz

09CA32261 File Number TC8314 Project Number: Page 55 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 55

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

: Block D: Lower Band edge Measurement method

: Down Link – Lowest channel = 1946.25 MHz (ch 325) Measured channel



09CA32261 File Number TC8314 Project Number: Page 56 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result – Plot no. 56

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block D: Higher Band edge

Measured channel



09CA32261 File Number TC8314 Project Number: Page 57 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 57

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

: Block B: Lower Band edge Measurement method

: Down Link – Lowest channel = 1951.25 MHz (ch 425) Measured channel



09CA32261 File Number TC8314 Project Number: Page 58 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 58

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block B: Higher Band edge

: Down Link – Highest channel = 1963.75 MHz (ch 675) Measured channel




Project Number: 09CA32261 File Number TC8314 Page 59 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

Center 1.965 000 GHz

Res BW 47 kHz

A1. Measurement result - Plot no. 59



VBW 47 kHz

Span 5 MHz

Sweep 2.76 ms (601 pts)

File Number 09CA32261 TC8314 Project Number: Page 60 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 60

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block E: Higher Band edge

: Down Link – Highest channel = 1968.75 MHz (ch 775) Measured channel



09CA32261 File Number TC8314 Project Number: Page 61 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 61

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

: Block F: Lower Band edge Measurement method

: Down Link – Lowest channel = 1971.25 MHz (ch 825) Measured channel



Project Number: 09CA32261 File Number TC8314 Page 62 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.


A1. Measurement result - Plot no. 62

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block F: Higher Band edge


Measured channel : Down Link – Highest channel = 1973.75 MHz (ch 875)

Operating condition : Max. Power output with modulated RF-carrier



Project Number: 09CA32261 File Number TC8314 Page 63 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.



09CA32261 File Number TC8314 Project Number: Page 64 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 64

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block C: Higher Band edge

: Down Link – Highest channel = 1988.75 MHz (ch 1175) Measured channel



09CA32261 File Number TC8314 Project Number: Page 65 of 66


Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 65

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

: Block G: Lower Band edge Measurement method

: Down Link – Lowest channel = 1991.25 MHz (ch 1225) Measured channel



09CA32261 File Number TC8314 Project Number: Page 66 of 66

Model Number: CDMA RF Repeater Client Name: SK Telesys Co., Ltd.

A1. Measurement result - Plot no. 66

Sub-clause : § 2.1051, § 24.238 - Spurious Emissions at Antenna terminal

Measurement method : Block G: Higher Band edge

: Down Link – Highest channel = 1993.75 MHz (ch 1275) Measured channel

