Test report No. : 11984035M-A-R2
Page : 24 of 27
Issued date : August 2, 2018
FCC ID : VBU-ALVBS2S

APPENDIX 3: Photographs of test setup

Radiated emission



Photo 1




Photo 2

UL Japan, Inc. Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Test report No. : 11984035M-A-R2
Page : 25 of 27
Issued date : August 2, 2018
FCC ID : VBU-ALVBS2S

Radiated emission




Photo 1




Photo 2

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

: 11984035M-A-R2 Test report No. Page : 26 of 27 : August 2, 2018 : VBU-ALVBS2S **Issued date** FCC ID

Worst Case Position

(Z-axis)


X-axis



Y-axis



Z-axis



1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan


Test report No. : 11984035M-A-R2
Page : 27 of 27
Issued date : August 2, 2018
FCC ID : VBU-ALVBS2S

With/Without MIFARE Card

with MIFARE Card



without MIFARE Card



MIFARE Card



End of Report

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan