Test report No. : 12729321M-A-R1
Page : 32 of 35
Issued date : June 17, 2019
FCC ID : VBU-V2HT

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1



Photo 2

UL Japan, Inc. Kashima EMC Lab.

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Test report No. : 12729321M-A-R1
Page : 33 of 35
Issued date : June 17, 2019
FCC ID : VBU-V2HT

Radiated Spurious Emission



Photo 1



Photo 2

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Test report No. : 12729321M-A-R1
Page : 34 of 35
Issued date : June 17, 2019
FCC ID : VBU-V2HT

Radiated Spurious Emission



Photo 1





Photo 2

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan

Test report No. : 12729321M-A-R1
Page : 35 of 35
Issued date : June 17, 2019
FCC ID : VBU-V2HT


Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)

X-axis



Y-axis

HT4



End of Report

1614, Mushihata, Katori-shi, Chiba-ken, 289-0341 Japan