

The test setup photos do not indicate that the appropriate minimum test configuration for PC
Peripherals was used during testing per ANSI C63.4. If the testing was performed using the
minimum configuration, please upload photos supporting this. If testing was not performed
with this configuration, then an updated test report with data using the appropriate
configuration will be required.

The revised Test Setup Photos has been uploaded to website.