


## **Inside view of EUT**



Report no. ETLE070605.375, Page D1 of D13

## **Inside view of EUT**



Report no. ETLE070605.375, Page D2 of D13




# Appendix D. Internal Photographs

#### Top side view of main board




Report no. ETLE070605.375, Page D3 of D13

#### **Bottom side view of main board**



Report no. ETLE070605.375, Page D4 of D13


## Top side view of inverter board



Report no. ETLE070605.375, Page D5 of D13




#### **Bottom side view of inverter board**



Report no. ETLE070605.375, Page D6 of D13


## Top side view of OSD board



Report no. ETLE070605.375, Page D7 of D13

ETLQP-21-F23-0

## **Bottom side view of OSD board**



Report no. ETLE070605.375, Page D8 of D13




## **View of PANEL**





Report no. ETLE070605.375, Page D9 of D13

#### **View of PANEL label**



#### View of I/O ports





Report no. ETLE070605.375, Page D10 of D13



## View of adapter





Report no. ETLE070605.375, Page D11 of D13




### View of adapter label



#### View of tuner



#### **Inside view of tuner**



Report no. ETLE070605.375, Page D13 of D13

**Head Office:** # 371-51 Gasan-dong, Geumcheon-gu, Seoul, 153-803, Korea Tel : 82-2-858-0786 Fax : 82-2-858-0788