

FCC Test Setup Photographs for

47CFR15, Subpart B for Unintentional Radiators, per Section 101 Equipment authorization of unintentional radiators,
And

47CFR15, Subpart C for Intentional Radiators, per Section 247
Operation within the bands 902 to 928 MHz

on

BridgePad RF by Quickpad IFCC ID:VFV-BPADRF]

Report number **20070524-01-F15**

Manufacturer
Quickpad Technology
465 Fairchild Dr. # 103
Mountain View, CA 94043
Judgement
Complies as tested

Tests and report by
ITC Engineering Services, Inc.
9959 Calaveras Road, P.O. Box 543
Sunol, California 94586
Tel.: (925) 862-2944
Fax: (925) 862-9013

E-Mail: docs@itcemc.com Web Site: www.itcemc.com








Report No.: 20070524-01-F15

Table of Contents	
PART 1 GENERAL INFORMATION	3
PART 2 Radiated Emissions Test Setup Photographs	4
PART 3 RF Measurements Setup Photographs	
List of Figures	List of Figures
Figure 1: Radiated Emissions Test Setup (Below 1 GHz) Rear View	4
Figure 2: Radiated Emissions Test Setup (Below 200MHz) Rear View	5
Figure 3: Radiated Emissions Test Setup (Below 1 GHz) Front View	6
Figure 4: Test Set Up Photos- RF Measurement (Front View)	7
Figure 5: RF Measurement Rear View (Above 1 GHz)	8

Prepared By: ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Email: docs@itcemc.com Fax: [925] 862-9013 Web: www.itcemc.com





PART 1 **GENERAL INFORMATION**

Applicant: Quickpad Technology

	1		
Product Type	Bridge RF (Battery Operated)		
Model	BpadRF		
Manufacturer's Name	QuickPad Technology		
Manufacturer's Address	465 Fairchild Dr. # 103		
	Mountain View, CA 94043		
	United States	Fax: +1 (650)916-9114	
	Tel: +1 (650) 961-9114	email: Henryk@quickpad.com	
Contact	Henryk Szejnwald	<u></u>	
Test Laboratory	ITC Engineering Services, Inc.		
-	9959 Calaveras Road,		
	PO Box 543		
	Sunol, CA 94586-0543		
	Email: docs@itcemc.com	Tel: +1(925) 862-2944	
	Web Site: http://www.itcemc.com	Fax: +1(925) 862-9013	
Test Number and Report Numbers	20070524-01	20070524-01-F15	
Test Date(s) & Issue Date	June 11 th - June 15 th ,2007	June 28th ,2007	
Test Engineer(s)	Sharmistha Modak		
Chief Engineer	Michael Gbadebo, P.E		
Documentation	Sharmistha Modak		
Test Results	☑ Complies as Tested	☐ Fail	

Prepared By: ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Email: docs@itcemc.com Fax: [925] 862-9013 Web: www.itcemc.com Product: BridgePad

FCC ID: VFV-BPADRF



PART 2 Radiated Emissions Test Setup Photographs



Figure 1: Radiated Emissions Test Setup (Below 1 GHz) Rear View

Prepared By: ITC Engineering Services, Inc.

9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Fax: [925] 862-9013 Email: docs@itcemc.com Web: www.itcemc.com



Applicant: Quickpad Technology Report No.: 20070524-01-F15



Figure 2: Radiated Emissions Test Setup (Below 200MHz) Rear View

Prepared By: ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Fax: [925] 862-9013 Email: docs@itcemc.com Web: www.itcemc.com





Figure 3: Radiated Emissions Test Setup (Below 1 GHz) Front View

Prepared By: ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Fax: [925] 862-9013 Email: docs@itcemc.com Web: www.itcemc.com



PART 3 RF Measurements Setup Photographs




Figure 4: RF Measurement (Front View)

Prepared By: ITC Engineering Services, Inc.

9959 Calaveras Road, PO Box 543 Sunol, California 94586-0543

Tel: [925] 862-2944 Fax: [925] 862-9013 Email: docs@itcemc.com Web: www.itcemc.com





Figure 5: RF Measurement Rear View (Above 1 GHz)

Prepared By: ITC Engineering Services, Inc. 9959 Calaveras Road, PO Box 543

Sunol, California 94586-0543

Tel: [925] 862-2944 Fax: [925] 862-9013 Email: docs@itcemc.com Web: www.itcemc.com Product: Bridge Pad RF

FCC ID:VFV-BPADRF