EXHIBIT A - FCC ID LABEL AND LOCATION

FCC ID Label

TOSHIBA

MICROWAVE OVEN MICKOWAYE OVEN
MODEL: EM134A2EW-POHAOO
INPUT 120V~60Hz,
INPUT:1500W 2450MHz
OUTPUT: 1100W MANUFACTURE DATE: MM YYYY



(חֶרְ) LISTED 54NJ E214180

CAUTION-THIS DEVICE IS TO BE SERVICED ONLY BY PROPERLY QUALIFIED SERVICE PERSONNEL. CONSULT THE SERVICE MANUAL FOR PROPER SERVICE PROCEDURES TO ASSURE CONTINUED COMPLIANCE WITH THE FEDERAL PERFORMANCE STANDARD FOR MICROWAVE OVENS AND FOR PRECAUTIONS TO BE TAKEN TO AVOID POSSIBLE EVENCULE TO EVESSIVE MICROWAVE FIRERGY EXPOSURE TO EXCESSIVE MICROWAVE ENERGY.

FCC ID: VG8EM134AYYW Contain FCC ID:VG8IOT10MP1 HOUSEHOLD USE ONLY (NOT FOR COMMERCIAL USE) MIDEA AMERICA CORP THIS DEVICE COMPLIES WITH DHHS RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J. MADE IN SHUNDE CHINA

WARNING: Cancer and Reproductive Harm-www.p65warnings.ca.gov

WARNING - TO ENSURE CONTINUED PROTECTION AGAINST ELECTRICAL SHOCK HAZARD, CONNECT TO PROPERLY GROUNDED OUTLETS ONLY.DISCONNECT APPLIANCE BEFORE SERVICING. REMOVAL OF OUTERCASE WITH PRODUCT ENERGIZED MAY EXPOSE SERVICEMAN TO HAZARDOUS HIGH VOLTAGE POTENTIALS. HAZARDOUS HIGH VOLTAGE POTENTIALS.

*CERTAIN INTERNAL PARTS ARE INTENTIONALLY NOT GROUNDED AND MAY PRESENT A RISK OF ELECTRIC SHOCK ONLY DURING SERVICING. SERVICE PERSONNEL -DO NOT CONTACT THE FOLLOWING PARTS WHILE THE APPLIANCE IS ENERGIZED: IF PROVIDED FAN MOTOR, TURNTABLE MOTOR, DAMPER MOTOR, L.V.TRANSFORMER (TOUCH CONTROL TYPE) OR TIMER MOTOR ASSEMBLY (MECHANICAL TYPE).


*RISK OF ELECTRIC SHOCK. NON-REMOVABLE FASTENERS ARE PROVIDED BECAUSE OF INTERNAL HIGH VOLTAGES.

DO NOT REMOVE FASTENERS.

* NOT FOR BUILT-IN INSTALLATION.

*PN:16070000B23020

FCC ID Label Location Information



Label here

Specifications:

Text is Black or white in color and is left justified. Labels are printed in indelible ink on permanent adhesive backing or silk-screened onto the EUT or shall be affixed at a conspicuous location on the EUT.