

FCC ID: VGBOPOFB503310 ETC Report No.: 09-01-MAS-054-01 Page B7 of B11


### 13. Front view of PCB2






FCC ID: VGBOPOFB503310 ETC Report No.: 09-01-MAS-054-01 Page B8 of B11


### 15. Front view of PCB3






FCC ID: VGBOPOFB503310 ETC Report No.: 09-01-MAS-054-01 Page B9 of B11


## 17. Front view of PCB4






FCC ID: VGBOPOFB503310 ETC Report No.: 09-01-MAS-054-01 Page B10 of B11

## 19. Front view of PCB5





FCC ID: VGBOPOFB503310 ETC Report No.: 09-01-MAS-054-01 Page B11 of B11

## 21. Front view of PCB6

