

Appendix D. Product Photos

Please refer to Sporton report number EP0D0647 as below.

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VGUZWP1 Page Number : D1 of D1
Report Issued Date : Dec. 16, 2010
Report Version : Rev. 01

Report No.: FA0D0647A




Report No.: FA0D0647A


Appendix E. Test Setup Photos




Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap



Holster 1 with Phantom 0 cm Gap



Holster 2 with Phantom 0 cm Gap

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VGUZWP1

Page Number : E1 of E1 Report Issued Date: Dec. 16, 2010

Report Version : Rev. 01