

Report No. : FR582514

Appendix A. Test Photos1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A1 of A6

Report Version

: Rev. 02



FCC Test Report No.: FR582514



Side view


SPORTON INTERNATIONAL INC. Page No. : A2 of A6
TEL: 886-3-327-3456 Report Version : Rev. 02

FAX: 886-3-327-0973



FCC Test Report **Report No. : FR582514**

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A3 of A6 Report Version : Rev. 02




FCC Test Report

Report No. : FR582514

For radiated emissions 30MHz~1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973


: A4 of A6 Page No. Report Version : Rev. 02




FCC Test Report

Report No. : FR582514

For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A5 of A6 : Rev. 02

Report Version