Draytek Corporation No. 26, Fu Shing Rd., Hukou County, Hsinchu Industrial Park, Hsinchu 303 Taiwan

## **DECLARATION OF SIMILARITY**

May 12, 2017

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

## Dear Sir or Madam:

We Draytek Corporation hereby declare that product: VDSL2 & ADSL2+ Dual-WAN Security Router, model(s): Vigor2862BLgVn, Series Model: Vigor2862Ln, Vigor2862LVn, Vigor2862LFN, Vigor2862LFVn, Vigor2862LgVn, Vigor2862LgFn, Vigor2862LgFVn, Vigor2862BLn, Vigor2862BLVn, Vigor2862BLFVn, Vigor2862BLFVn, Vigor2862BLgn, Vigor2862BLgVn, Vigor2862BLgFn, Vigor2862BLgFVn, Vigor2926Ln, Vigor2926LVn, Vigor2926LFn, Vigor2926LFVn, Vigor2926Lgn, Vigor2926LgVn, Vigor2926LgFn, Vigor2926LgFVn, Vigor2860Ln, Vigor2860LVn, Vigor2860LFn, Vigor2860LFVn, Vigor2860Lgn, Vigor2860LgVn, Vigor2860LgFn, Vigor2860LgFVn, Vigor2860BLn, Vigor2860BLVn, Vigor2860BLFn, Vigor2860BLFVn, Vigor2860BLgn, Vigor2860BLgVn, Vigor2860BLgFn, Vigor2860BLgFVn, Vigor2925Ln, Vigor2925LVn, Vigor2925LFn, Vigor2925LFVn, Vigor2925Lgn, Vigor2925LgVn, Vigor2925LgFn, Vigor2925LgFVn, Vigor2862n, Vigor2862Vn, Vigor2862Fn, Vigor2862FVn, Vigor2862Bn, Vigor2862BVn, Vigor2862BFn, Vigor2862BFVn, Vigor2926n, Vigor2926Vn, Vigor2926Fn, Vigor2926FVn, Vigor2860n, Vigor2860Vn, Vigor2860Fn, Vigor2860FVn, Vigor2860Bn, Vigor2860BVn, Vigor2860BFn, Vigor2860BFVn, Vigor2925N, Vigor2925Vn, Vigor2925Fn, Vigor2925FVn, Vigor2832n, Vigor2832Vn are electrically identical with the same electromagnetic emissions and electromagnetic compatibility characteristics as model: Vigor2862BLgVn tested by BACL, the results of which are featured in BACL project: RTWA170214001.

QA-FR-227-A 11/05/2013

A description of the differences between the tested model and those that are declared similar are as follows:

2862, 2860, 2832, has dsl function

2926, 2925 didn't has dsl function

2862, 2860, 2832 for different marketing

2926, 2925 for different marketing

n Only 2.4G Wi-fi function

F Fiber function

V VoIP function

L LTE function

B Bonding VDSL function

g GPS function

Please contact me should there be need for any additional clarification or information.

Best Regards,

Abbott Yu/ HW manager

No. 26, Fu Shing Rd., Hukou County, Hsinchu Industrial Park, Hsinchu 303 Taiwan

QA-FR-227-A 11/05/2013