

Page : 1 of 3
Issued date : Jun. 5, 2019
FCC ID : VGY2620

Radiated Spurious Emission Setup Configurations

Above 1GHz





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948


Doc No: 17-EM-F0876 / 1.0



Page : 2 of 3
Issued date : Jun. 5, 2019
FCC ID : VGY2620

Below 1GHz





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan


Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948


Doc No: 17-EM-F0876 / 1.0



Page : 3 of 3 Issued date : Jun. 5, 2019 FCC ID : VGY2620

AC Power Line Conducted Emission Setup Configurations





Underwriters Laboratories Taiwan Co., Ltd.

Building B and Building E, No. 372-7, Sec. 4, Zhongxing Rd., Zhudong Township, Hsinchu County, Taiwan

Telephone :+886-2-7737-3000 Facsimile (FAX) :+886-3-583-7948

Doc No: 17-EM-F0876 / 1.0