Draytek Corporation No. 26, Fu Shing Rd., Hukou County, Hsinchu Industrial Park, Hsinchu 303 Taiwan

## DECLARATION OF SIMILARITY

May 12, 2017

FEDERAL COMMUNICATIONS COMMISSIONS Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

Dear Sir or Madam:

We Draytek Corporation hereby declare that product: VDSL2 & ADSL2+ Dual-WAN

Security Router, model(s): Vigor2862BLgVac, Series Model:Vigor2862Lac,

Vigor2862LVac,

Vigor2862LFac, Vigor2862LFVac, Vigor2862Lgac, Vigor2862LgVac, Vigor2862LgFac, Vigor2862LgFvac, Vigor2862BLgVac, Vigor2862BLgFvac, Vigor2926Lac, Vigor2926LVac, Vigor2926LFac, Vigor2926LFac, Vigor2926LFVac, Vigor2926Lgac, Vigor2926LgVac, Vigor2926LgFac, Vigor2926LgFvac, Vigor2860Lac, Vigor2860LVac, Vigor2860LFac, Vigor2860LFvac, Vigor2860LgFac, Vigor2860LgFac, Vigor2860LgFvac, Vigor2860LgFvac, Vigor2860BLgVac, Vigor2860BLgFvac, Vigor2925Lac, Vigor2925LVac, Vigor2925LFac, Vigor2925LFvac, Vigor2925Lgac, Vigor2925LgFac, Vigor2925LgFvac, Vigor2925LgFac, Vigor2925LgFvac, Vigor2925LgFac, Vigor2926Vac, Vigor2926Fac, Vigor2926Fac, Vigor2926Fac, Vigor2926Fac, Vigor2926Fac, Vigor2925Fa, Vigor2925Fvac are electrically identical with the same electromagnetic emissions and electromagnetic compatibility characteristics as model: Vigor2862BLgFvac tested by BACL, the results of which are featured in BACL project: RTWA170214001.

A description of the differences between the tested model and those that are declared similar are as follows:

2862 ,2860 ,2832,has dsl function 2926 ,2925 didn't has dsl function 2862 ,2860 ,2832 for different marketing 2926 ,2925 for different marketing

QA-FR-227-A 11/05/2013

- ac 2.4G Wi-fi function and 5G Wi-fi function
- F Fiber function
- V VoIP function
- L LTE function
- B Bonding VDSL function
- g GPS function

Please contact me should there be need for any additional clarification or information.

Best Regards,

Abbott Yu/ HW manager

No. 26, Fu Shing Rd., Hukou County, Hsinchu Industrial Park, Hsinchu 303 Taiwan

QA-FR-227-A 11/05/2013