

Inside view of EUT



Report no. ETLE140205.0166, Page D1 of D11




Inside view of EUT



Report no. ETLE140205.0166, Page D2 of D11



Inside view of EUT



Report no. ETLE140205.0166, Page D3 of D11



Top side view of main board



Report no. ETLE140205.0166, Page D4 of D11



Bottom side view of main board



Report no. ETLE140205.0166, Page D5 of D11



Top side view of Chip Antenna



Report no. ETLE140205.0166, Page D6 of D11



Top side view of laser board



Report no. ETLE140205.0166, Page D7 of D11




Bottom side view of laser board



Report no. ETLE140205.0166, Page D8 of D11




Top side view of USB board



Report no. ETLE140205.0166, Page D9 of D11



Bottom side view of USB board




Report no. ETLE140205.0166, Page D10 of D11



View of Li-Polymer battery





Report no. ETLE140205.0166, Page D11 of D11