
TEST REPORT: 1082 FCC ID: VHY3271-1 Page 40 of 42

Photograph 8 - View of the RF Front-end PCBs



TEST REPORT: 1082 FCC ID: VHY3271-1

Page 41 of 42

Photograph 9 - View of the Protocol Converter PCBs





Protocol converter mother board Top view



Protocol converter mother board Bottom view



Moxa Ethernet board Top view

Moxa Ethernet board Bottom view

Protocol converter board assembly



Protocol converter mother board assembly with Moxa Top view

TEST REPORT: 1082 FCC ID: VHY3271-1

Page 42 of 42

Photograph 10 - View of the Accessory Assemblies



Accessory assemblies



13dB Attenuator Top view



13dB Attenuator Bottom view



1GHz filter Top view



1GHz filter Bottom view



Status Indicator board Bottom view



Status Indicator board Top view