REPORT NO. : FR772516


APPENDIX B. Internal Photographs of EUT



SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: VIBLBT313 Page Number : B1 OF B4
Report Issued Date : Aug, 22, 2007
Report Version : Rev. 01






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: VIBLBT313 Page Number : B2 OF B4
Report Issued Date : Aug, 22, 2007
Report Version : Rev. 01






SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: VIBLBT313 Page Number : B3 OF B4
Report Issued Date : Aug, 22, 2007
Report Version : Rev. 01





SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: VIBLBT313 Page Number : B4 OF B4
Report Issued Date : Aug, 22, 2007
Report Version : Rev. 01