













PAGE NUMBER : B7 OF B25
ISSUED DATE : Mar. 13, 2008






PAGE NUMBER : B8 OF B25
ISSUED DATE : Mar. 13, 2008
















TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B11 OF B25
ISSUED DATE : Mar. 13, 2008








ISM Receiver Ant.




GPS module & Ant.











TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B14 OF B25
ISSUED DATE : Mar. 13, 2008










PAGE NUMBER : B16 OF B25
ISSUED DATE : Mar. 13, 2008




FM module




SPORTON International Inc.


TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B17 OF B25
ISSUED DATE : Mar. 13, 2008



Bluetooth module




SPORTON International Inc.





TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B19 OF B25
ISSUED DATE : Mar. 13, 2008



TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 PAGE NUMBER : B20 OF B25
ISSUED DATE : Mar. 13, 2008