

## TUNE UP PROCEDURE

REF: ATCB 06 REV: 00

DATE: MAR 24/2010

## As required by 2.1033(c)(9 a "Tune Up" document must be provided, i.e. a description of how and to what tolerance the power is adjusted during manufacturing.

Not applicable in our case:

This product is factory tuned, opeartes only on fixed frequencies and contains no user-tunable components

Each beacon is checked in manufacturing:

- 406 MHz must be 37 dBm  $\pm$  2dB
- 121.5 MHz must be 17 dBm  $\pm$  3dB

A final inspection is performed on each beacon and Acceptance Test Reports are filled to prove that they are compliant with these specifications before release.