



## INTERTEK TESTING SERVICES

### Internal photos





---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

## INTERTEK TESTING SERVICES

---


### Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos




---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

INTERTEK TESTING SERVICES

## **Internal photos**





---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

## INTERTEK TESTING SERVICES



---

### Internal photos



**INTERTEK TESTING SERVICES**

## **Internal photos**




---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

## INTERTEK TESTING SERVICES

### Internal photos





---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

## INTERTEK TESTING SERVICES

---

### Internal photos





---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

## INTERTEK TESTING SERVICES

### Internal photos





---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM

# INTERTEK TESTING SERVICES

## Internal photos




---

FCC ID: VIXPNMDUALCAM  
IC: 21578-PNMDUALCAM



# INTERTEK TESTING SERVICES

## Internal photos




## INTERTEK TESTING SERVICES

### Internal photos




## INTERTEK TESTING SERVICES

### Internal photos



## INTERTEK TESTING SERVICES

### Internal photos



## INTERTEK TESTING SERVICES

---

### Internal photos

