INTERTEK TESTING SERVICE

Report No: 17010529HKG-002

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Front View)

Model: TT100



FCC ID: VIXTT100 IC: 21578-TT100

INTERTEK TESTING SERVICE

Report No: 17010529HKG-002

Configuration Photographs

Worst-Case Line-Conducted Emissions

(Rear View)

Model: TT100



FCC ID: VIXTT100 IC: 21578-TT100

INTERTEK TESTING SERVICE

Report No: 17010529HKG-002

Configuration Photographs Worst-Case Line-Conducted Emissions

(Side View)

Model: TT100



FCC ID: VIXTT100 IC: 21578-TT100