



INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES


Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M


INTERTEK TESTING SERVICES

Internal photos





INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES



Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M

INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES


Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M


INTERTEK TESTING SERVICES

Internal photos



INTERTEK TESTING SERVICES

Internal photos



FCC ID: VIXPNMDUAL5M
IC: 21578-PNMDUAL5M