Test report No. : 10037307H-B Page : 32 of 33

Issued date : September 11, 2013 FCC ID : VIYARC0540

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124

Test report No. : 10037307H-B Page : 33 of 33

Issued date : September 11, 2013 FCC ID : VIYARC0540

Worst Case Position (Horizontal: Y-axis/ Vertical: Z-axis)







End of Report

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999 Facsimile : +81 596 24 8124