Test report No. : 32JE0006-HO-01-B

Page : 31 of 32 Issued date : June 28, 2012 FCC ID : VIYARC0503

## **APPENDIX 3: Photographs of test setup**

# **Radiated Spurious Emission**



Photo 1




Photo 2

# UL Japan, Inc.

#### **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 32JE0006-HO-01-B


Page : 32 of 32 Issued date : June 28, 2012 FCC ID : VIYARC0503

## Worst Case Position (Horizontal: X-axis/ Vertical: Z-axis)

#### X-axis



Y-axis





**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124