

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

August 8, 2007

RE: Smart Christmas Solutions

FCC ID: VJK73833T49

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) FYI...It is noted that for the fundamental that both peak and average data was provided. Note that it is uncertain if this carrier is pulsed or not. If the carrier is pulsed (i.e. pulses are seen when looking at the carrier with 0 Hz. span), then the average should have been calculated and not measured. Given that the peak carrier meets average limits, further investigation is not being taken in this application.
- 2) FYI...The RX portion of this system requires either a DoC or Certification as a PC peripheral device and a RX (composite device). Also, please note that currently MRA's do not allow for DoC's to be performed by Chinese Labs. If necessary, for more information, please contact Jerry or Wailand.

Timothy R. Johnson Examining Engineer

mailto: tjohnson@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.