

Washington Laboratories, Ltd.

7560 LINDBERGH DRIVE GAITHERSBURG, MD 20879 (301) 417 – 0220 FAX # (301) 417 - 9069

March 10, 2008

WLL Project: 9936

Mr. Tim Johnson American Telecommunications Certification Body Inc. 6731 Whittier Ave McLean, VA 22101

RE: Comments (2) for SYSTEM-100

APPLICATION: VKC-SYSTEM100 Stanley Innerspace

Dear Mr. Johnson:

Below are the comments that you have provided regarding the application for certification referenced above. Our responses to those comments are in *bold italic*. Many responses refer you to additional exhibit(s) which has been uploaded to the application folder at the ATCB website.

Thank you for your attention. Please feel free to contact us for any additional information that you may require.

Regards,

Steven D. Koster EMC Operations Manager

Brian J. Dettling
Documentation Specialist

- 1) While schematics of the RF reader have been provided, there are not any component values. Kindly provide an updated schematic, or optionally, provide a parts list to go with the schematic. If a parts list is provided separately, please be sure to update the confidentiality letter as necessary.
- R. Please see "ID ISCPR101-PartList". The confidential request letter includes Parts Lists.
- 2) Are conducted photos with actual antennas available as well?
- R. Photos were taken at the conclusion of testing with the dummy load in place.
- 3) Your response mentions the device/system complies with Part 15 Class A levels, but the manual still cites Class B. Please review/explain.

- R. Please see updated User Manual "System 100 User Guide R8 edit 3.08".
- 4) Regarding previous comment 12), this information was not found in the manual. Kindly explain where this may be found.
- R. Please see updated User Manual.