Tom Cokenias

From: Tom Cokenias

Sent: Thursday, August 09, 2007 4:07 PM

To: tbarth@dtection.com

Cc: Tom Cokenias; Thu Chan; Tom Cokenias

Subject: Dtection, Incorporated, FCC ID: VKG-0016641284, Assessment NO.: AN07T7015, Notice#3

Dear Mr Barth,

The following issues must be addressed before processing can continue on this application:

Your grantee code has been corrected to VKG. I have updated the CCS internal records, however, you will need to re-submit the attachments with the correct FCC ID code.

The new FCC ID code is VKG-0016641284, the same as before except with the correct grantee code VKG.

The following documents must be resubmitted and must show the correct $FCC\ ID$:

- 1. FCC label drawing
- 2. Test report
- 3. Letter requesting confidentiality under 0.459 of the Rules
- 4. Test set-up photographs

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.