

August 27, 2007

RE: ATCB005350

FCC ID: VLEAE20004

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

- 1. For bandedge emission shown on the spectrum plots at page 8 was measured with modulating signal, please describe why the modulating signal can not be turned off.
- 2. Please provide an operational description that meets the requirements of 2.1033.

- ~ George Chen
- ~ mailto:george@atcb.com
- ~ Taiwan Mobile: +886 930600123
- ~ SKYPE: georgeshirley

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.