


Report No: CCIS14020004905

8 **Test Setup Photo**






Radiated Spurious Emission



Telephone: +86 (0) 755 2311 8282 Fax: +86 (0) 755 2311 6366



Report No: CCIS14020004905



Telephone: +86 (0) 755 2311 8282 Fax: +86 (0) 755 2311 6366

Project No.: CCIS140200049RF