Internal photos





Test Report Number: 16051965HKG-001 FCC ID: VLJ-MBP482BU

FCC ID: VLJ-MBP482BU IC: 4522A-MBP482BU

Internal photos






Test Report Number: 16051965HKG-001 FCC ID: VLJ-MBP482BU

FCC ID: VLJ-MBP482BU IC: 4522A-MBP482BU

Internal photos






Test Report Number: 16051965HKG-001 FCC ID: VLJ-MBP482BU

IC: 4522A-MBP482BU

Internal photos






Test Report Number: 16051965HKG-001 FCC ID: VLJ-MBP482BU

IC: 4522A-MBP482BU

Internal photos



Test Report Number: 16051965HKG-001 FCC ID: VLJ-MBP482BU

IC: 4522A-MBP482BU