## **BINATONE TELECOM PLC**

1 Apsley Way London NW2 7HF, United Kingdom. Tel: +44(0) 20 8955 2700 Fax: +44(0) 20 8344 8877

e-mail: binatoneuk@binatonetelecom.co.uk



18 Sept, 2017

## Application for Permissive Change of FCC ID: VLJ-MBP38SPU, IC: 4522A-MBP38SPU

Dear Sir/Madam:

The purpose of this document is to describe all the changes made on the certified transmitter with FCC ID: VLJ-MBP38SPU, IC: 4522A-MBP38SPU

## **Modification:**

- Replace the rechargeable Battery.
- Replace the Battery charging IC.
- There is change in the size of the battery compartment.
- There is a minor change in the PCB layout to fit the new battery charging IC.
- Add some de-coupling capacitor at LCD signal.
- Remove the ferrite bead on the AC-DC adaptor.

## <u>Similarities between the certified equipment:</u>

- No change in the RF part. RF IC, RF circuit, PCB layout of the RF circuit, RF Antennas are identical to the certified equipment.
- MCU are identical to the certified equipment.
- Functionality and intended usage are identical to the certified equipment.
- Outlook is identical to the certified equipment.
- Rating is identical to the certified equipment.

Sincerely,

(Grantee contact signature)

Name: Karl Heinz Mueller Title: Chief Technical Officer