
Internal photos






Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU

Internal photos






Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU

FCC ID: VLJ-MBP140BU IC: 4522A-MBP140BU

Internal photos





Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU


Internal photos






Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU

Internal photos





Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU

Internal photos



Test Report Number: 16051055HKG-001 FCC ID: VLJ-MBP140BU