Test report No. : 30CE0152-HO-03-A

Page : 11 of 19 Issued date : January 13, 2010 FCC ID : VM6WD30

APPENDIX 1: Photographs of test setup

Radiated Spurious Emission



Photo 1




Photo 2

UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 30CE0152-HO-03-A

Page : 12 of 19 Issued date : January 13, 2010 FCC ID : VM6WD30

Worst Case Position (Horizontal: Y-axis/ Vertical: X-axis)

Antenna: WD30-AT002







Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124