

American Telecommunications Certification Body Inc.

6731 Whittier Ave, McLean, VA 22101

October 3, 2007

RE: ATCB005485

FCC ID: VN2XW20078

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

- 1. FCC Logo can be only shown on the label as this device has been tested under Part 15B. This device is not a computer peripheral, therefore it is not required to be test under Part 15B. Please remove the FCC logo from the label.
- It is required to put the crystal oscillator with frequency value on your block diagram according to the FCC 2.1031.
 - "FCC 2.1031 (5) A block diagram showing the frequency of all oscillators in the device. The signal path and frequency shall be indicated at each block. The tuning range(s) and intermediate frequency(ies) shall be indicated at each block."
- 3. The description shown on the photo at page 2 of the test report can not be seen clearly. Please provide a better photo showing description clearly.

- ~ George Chen
- ~ mailto:george@atcb.com
- ~ Taiwan Mobile: +886 930600123
- ~ SKYPE: georgeshirley

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.