

BABT

29 November 2007 Ref: US-000163

To FCC

BABT Balfour House, Churchfield Road Walton on Thames Surrey, KT12 2TD United Kingdom Telephone: +44 (0)1932 251200 Fax: +44 (0)1932 251201

Direct Dial: +44 (0)1932 251261 E-mail: Vina.Kerai@babt.com Website: www.babt.com

## Overall Assessment Letter for Cisco851 802.11b/g radio

FCC id: VN9CISTCM123

I have reviewed this application and find it compliant. This is an application for a change in FCC ID for the originally filed Cisco851 802.11b/g radio with FCC ID LDKXSNIAG13 under TCM Mobile Limited (TCM) FCC ID VN9CISTCM123.

The FCC ID label and photos of the exterior of the equipment have been provided. While reviewing the label it was noticed that the ACTA registration shown in the label exhibit is the Cisco ACTA registration. TCM has applied for a RPC and the identifier TCM will be using for the router is DL01B0144 as stated in their FCC 47 CFR compliance letter. The label will be corrected in a class 1 permissive change application.

The TCM covering letter contains their user manual declaration wherein it is stated that the same user manual will be supplied and no changes will be made to the original user manual. An addendum to the user manual has been provided by TCM which states that the original user manual now additionally relates to FCC ID VN9CISTCM123.

Yours sincerely

Vina Kerai

Compliance Engineer

