



Balfour House, Churchfield Road Walton on Thames Surrey, KT12 2TD United Kingdom Telephone: +44 (0)1932 251200 Fax: +44 (0)1932 251201

BABT

Direct Dial: +44 (0)1932 251261 E-mail: Vina.Kerai@babt.com Website: www.babt.com

7 January 2008 Ref: US/000166

To: FCC

Overall Assessment Letter for TCM Mobile System - TCM-BST-001 FCC id: VN9BST001

I have reviewed this application and find it compliant.

This application relates to an approval for a TCM amplifier which includes TCM housing for use with the module with FCC ID VN9CISTCM123.

Please note the following:

1: Sparklan Unit

The unit does have a Sparklan unit, however TCM have provided a cover letter, 'Sparklan - No operational Statement' where they state that the unit is not connected to the power supply or to any other components and the use of Sparklan is inhibited.

2: Oscillators

TCM have provided confirmation that the unit does not contain any oscillators. Please refer to their cover letter, 'System - No Oscillators Statement.doc'.

3: RF Exposure

This application approves the router for use in the TCM Host. This host meets occupation and general public exposure limits and an RF Exposure test report has been provided to demonstrate compliance. The RF Exposure test report with Doc Number 75901050 Report 01 Issue 1 states a part number of TCM-BS-T001 instead of TCM-BST-001. This is simply a typographical error and the number should have been recorded with the dash (-) character being placed after the 'T' and not before the 'T'.

I underwent the FCC RF exposure evaluation training at BABT in July 2007.

Yours sincerely

Vina Kerai

Compliance Engineer, BABT

