EXHIBIT 13



November 14,2007

BABT TCB
Balfour House
Churchfield Road
Walton-on-Thames
Surrey
KT12 2TD

We hereby state and confirm the following:

- TCM Mobile Ltd. ("TCM) is requesting a change of FCC ID for the Cisco851 802.11 b/g radio ("Router") and to obtain its own FCC ID for it.
- 2. New intended FCC ID: VN9CISTCM123
- 3. The original FCC ID: LDKXSNIAG13
- 4. The date of the original grant of the Router: April 28 2005
- 5. The dates of any permissive changes to the original product: **March 19 2007**:
- 6. The only difference between the original Router to the Router TCM is requesting its own FCC ID for, is the label. The label will have the new intended FCC ID and the TCM name on it.
- 7. All of the original test results are applicable to the "new" product
- 8. TCM will use the same User Manual of the Router and will not make any changes to the User Manual whatsoever.

Sincerely,

Avi Shani - CEO

Carmi Peleg - CTO

TCM Mobile Ltd 11 Amal St. Rosh Ha'ayin 48092 Israel

> Tel: 077-7866617 Fax: 03-9013714