

December 12, 2007

BABT TCB
Balfour House
Churchfield Road
Walton-on-Thames
Surrey
KT12 2TD

We hereby state and confirm the following:

- 1. TCM Mobile Ltd. ("TCM) is requesting a *Permissive Change to the* Cisco851 802.11 b/g radio ("Router"), FCC ID: VN9CISTCM123.
- 2. The testing reported in TÜV Product Service report no. 75901050 Report 02 Issue 1 and TÜV Product Service report no. 75901050 Report 01 Issue 1 which refer to FCC id: VN9BST001 are all relevant and accurate to FCC id: VN9CISTCM123. This is because the equipment tested is identical in both FCC id: VN9BST001 and FCC id: VN9CISTCM123. Only the FCC id has changed and no other aspects of the equipment under test.

Sincerely,

Avi Shani - CEO

Carmi Peleg - CTO

TCM Mobile Ltd 11 Amal St. Rosh Ha'ayin 48092 Israel Tel: 077-7866617

Fax: 03-9013714