

Federal Communications Commission 7435 Oakland Mills Road Columbia, MD 21046

Re: Compliance Statement in Fork-Lift Truck Manual / FCC ID: VNQ-0200201

Dear Sirs,

Our client's products with the above FCC ID code are low frequency transmitters. The products will be installed in fork-lift trucks before they will be placed into the market.

Hereby our client assures that the following caution statement as per CFR 47, Part 15, § 15.21 will be included in the owner's manual of the cars:

The title "CAUTION TO USERS" or "FCC Warning:" "NOTE:" or relevant title and "Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment."

In addition our client also assures that the following statement will be included in the manual as per CFR 47, Part 15, § 15.19 (a) (3).

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) this device may not cause harmful interference, and
- (2) this device must accept any interference received, including interference that may cause undesired operation.

Strasskirchen, 04.10.2007

Sincerely,

Thomas Ring

Thomask

Manager Certification

mikes-testingpartners gmbh Ohmstrasse 2-4 94342 Strasskirchen, Germany Phone: ++49 9424 9481 0

Fax: ++49 9424 9481 240

FCC Notice Model JXP-HPS

Model JXP-HPS has been granted the following certification numbers:

FCC-ID: VNQ-0200201 IC: 7350A-0200201

FCC conditions

This device complies with part 15 of the FCC Rules. Operation is subject to the following conditions:

- (1) This device may not cause harmful interference.
- (2) This device must accept any interference received, including interference that may cause undesired operation.

Any changes or modifications not expressly approved by the party responsible for compliance would void the user's authority to operate the equipment.