INTERTEK TESTING SERVICE

Report No: HK09030474-5

Configuration Photographs

Worst-Case Radiated Emissions

(Front View)

Model: 3565



Fig.1

FCC ID: VNY-ULT3565

INTERTEK TESTING SERVICE

Report No: HK09030474-5

Configuration Photographs

Worst-Case Radiated Emissions

(Back View)

Model: 3565




Fig.2