Test Report No. : 29GE0009-HO-01-A-R1


Page : 18 of 43 Issued date : March 6, 2009 Revised date : March 31, 2009 FCC ID : VOSFL-M1000A

## **APPENDIX 1: Photographs of test setup**

### **RF Output Power**




**Audio Frequency Response** 



Emission limitations, Spurious emission at Antenna Terminal, 99% Occupied Bandwidth

**Modulation Limiting** 



Frequency Stability



# UL Japan, Inc. Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test Report No. : 29GE0009-HO-01-A-R1

Page : 19 of 43 Issued date : March 6, 2009 Revised date : March 31, 2009 FCC ID : VOSFL-M1000A


### Field Strength of Spurious Emission (below 1GHz)





Field Strength of Spurious Emission (above 1GHz)





# UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124