

## 4.6 Test Photographs



Front View



Rear View

TEL: +86-512-6917-5888 FAX: +86-512-6917-5666

Issued date : Sep. 15, 2014


Report No.: TEFI1405146

Page No. : 24 of 108


FCC ID : VP5ODC202AC



## 5.8 Test Photographs (30MHz~1GHz)



Front View



Rear View

Cerpass Technology (Suzhou) Co., Ltd

TEL: +86-512-6917-5888 FAX: +86-512-6917-5666

Issued date : Sep. 15, 2014


Report No.: TEFI1405146

Page No. : 57 of 108


FCC ID : VP5ODC202AC



## 5.9 Test Photographs (Above 1GHz)



Front View



Rear View

Cerpass Technology (Suzhou) Co., Ltd

TEL: +86-512-6917-5888 FAX: +86-512-6917-5666

Issued date : Sep. 15, 2014

Report No.: TEFI1405146

Page No. : 58 of 108

FCC ID : VP5ODC202AC