Chris Harvey

From: miura-katsunori [miura-katsunori@jqa.jp]
Sent: Thursday, November 22, 2007 6:33 AM

To: charvey-tcb@ccsemc.com

Cc:

Subject: Re: KATSURAGAWA ELECTRIC CO., LTD., FCC ID: VP8-K115, Assessment NO.:

AN07T7370, Notice#1

Attachments: Exhibit L1-User's Manual_R.pdf; Exhibit M1-Test Report_R.pdf





Exhibit L1-User's Manual_R.pdf...

Exhibit M1-Test Report_R.pdf (...

Dear Harvey

Thank you very much for your early review and reply. And, I am writing to you regarding the comments from you.

For #1:

My cliant understood your comment.

I attached the correct documents.

Please confirm file number "Exhibit L1-User's Manual_R".

For #2:

This RFID is used to judge the toner of the manufacturers specification with built-in IC chip.

The measured printer does not operate if this mechanism does not consist.

The printer was measured by the operating state.

Therefore, there is a description of co-location in the test report.

Others:

I am sorry that the submitted test report have clerical errors.

The clerical errors is the description of moduration(in page 4).

I attached the correct documents.

Please confirm file number "Exhibit M1-Test Report_R".

Sincerely yours,

Katsunori Miura

QUALITY ASSURANCE ORGANIZATION TESTING DIV.

EMC ENGINEERING DEPT.

SAFETY & EMC CENTER Tel: +81-3-3416-0193

Fax: +81-3-3416-8290

e-mail: miura-katsunori@jqa.jp

---- Original Message ---From: <charvey-tcb@ccsemc.com>
To: <miura-katsunori@jqa.jp>
Cc: <charvey-tcb@ccsemc.com>

Sent: Saturday, November 17, 2007 12:12 AM

Subject: KATSURAGAWA ELECTRIC CO., LTD., FCC ID: VP8-K115, Assessment NO.:

AN07T7370, Notice#1

> Dear Miura Katsunori-san ,

```
> You are listed as the Technical Contact for the above referenced TCB
> application. The following item(s) need(s) to be resolved before the
> review can be continued:
> 1. The Users Manual statements required by the FCC are incorrect in the
> manual submitted. This appears to be a Class A Digital Device that also
> contains this RFID Reader & Writer. This would require that the
> statements from FCC 15.105(a) and FCC 15.21 would be required. Since the
> statement from FCC 15.19 is already on the label, it is not required to be
> located in the manual, but it is OK to also include it in the Manual.
> Please submit an updated Users Manual.
> The required text is copied here for your reference:
> FCC 15.105(a)
> NOTE: This equipment has been tested and found to comply with the limits
> for a Class A digital device, pursuant to part 15 of the FCC Rules. These
> limits are designed to provide reasonable protection against harmful
> interference when the equipment is operated in a commercial environment.
> This equipment generates, uses, and can radiate radio frequency energy
> and, if not installed and used in accordance with the instruction manual,
> may cause harmful interference to radio communications. Operation of this
> equipment in a residential area is likely to cause harmful interference in
> which case the user will be required to correct the interference at his
> own expense.
> FCC 15.21
> Changes or modifications not expressly approved by the party responsible
> for compliance could void the user's authority to operate the equipment.
> 2. The test report states that this transceiver is used in combination
> with a permanently co-located transmitter, but does not explain what that
> 'other transmitter' is. Please provide further description of the
> co-location.
> The items indicated above must be submitted before processing can continue
> on the above referenced application. Failure to provide the requested
> information within 30 days of the original e-mail date may result in
> application dismissal and forfeiture of the filing fee. Also, please note
> that partial responses increase processing time and should not be
> submitted. Any questions about the content of this correspondence should
> be directed to the e-mail address listed below the name of the sender.
> Best regards,
>
> Chris Harvey
> Charvey-tcb@ccsemc.com
```