Appendix B. Internal Photographs of EUT



SPORTON International Inc.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B1 OF B21
Report Issued Date : Oct. 29, 2007

Report No. : FG751505-03


Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B2 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B3 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B4 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B5 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B6 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B7 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B8 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B9 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B10 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B11 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B12 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B13 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B14 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B15 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B16 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B17 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B18 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B19 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B20 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: VPV-GP810 Page Number : B21 OF B21
Report Issued Date : Oct. 29, 2007
Report Version : Rev.01