
# Appendix C. Photographs of Setup

## **Conducted Emission**

Mode 1-2 and 4



FRONT VIEW



**REAR VIEW** 

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C4
Report Issued Date : Oct. 26, 2007
Report Version : Rev. 01

Report No. : FR751505-02





SIDE VIEW

#### Mode 3




FRONT VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C4
Report Issued Date : Oct. 26, 2007
Report Version : Rev. 01





**REAR VIEW** 



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C3 of C4
Report Issued Date : Oct. 26, 2007
Report Version : Rev. 01

### Report No. : FR751505-02

## **Radiation Emission**

Mode 1-3



FRONT VIEW

REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C4 of C4
Report Issued Date : Oct. 26, 2007
Report Version : Rev. 01