From: Steve Hoke [shoke@pseinc.com]
Sent: Monday, December 17, 2007 1:39 PM

To: Sid Sanders

Subject: Stormeasy shutter replacement plot

Hi Sid,

Sorry for the issue with the FCC. It was my fault. I added the FCC ID number to the page as requested by one of your review engineers and by doing so I inadvertently covered up the (5 dB/div) on the plot. I attached the plot with the FCC ID moved over slightly.

Let me know if you need anything else.

Thanks,

Steve Hoke EMC Site Manager - Product Safety Engineering 12955 Bellamy Bros. Blvd. Dade City, FL 33525

Tel - 352-588-2209 X104 Fax - 352-588-2544

THE INFORMATION CONTAINED IN THIS ELECTRONIC MAIL TRANSMISSION IS CONFIDENTIAL AND MAY ALSO CONTAIN PRIVILEGED INFORMATION OR WORK PRODUCT. THE INFORMATION IS INTENDED ONLY FOR THE USE OF THE INDIVIDUAL OR ENTITY TO WHOM IT IS ADDRESSED. IF YOU ARE NOT THE INTENDED RECIPIENT, YOU ARE HEREBY NOTIFIED THAT ANY USE, DISSEMINATION, DISTRIBUTION OR COPYING OF THIS COMMUNICATION IS STRICTLY PROHIBITED. IF YOU HAVE RECEIVED THIS ELECTRONIC MAIL TRANSMISSION IN ERROR, PLEASE IMMEDIATELY ERASE AND DELETE THE ORIGINAL MESSAGE FROM YOUR DATABASE.