Test report No. : 11489808H-A
Page : 46 of 48
Issued date : November 15, 2016
FCC ID : VPYLB1KA

APPENDIX 3: Photographs of test setup

Conducted Emission




Photo 1




Photo 2

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

Test report No. : 11489808H-A
Page : 47 of 48
Issued date : November 15, 2016
FCC ID : VPYLB1KA

Radiated Spurious Emission




Photo 1





Photo 2


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone: +81 596 24 8999 Facsimile: +81 596 24 8124

: 11489808H-A Test report No. Page : 48 of 48 Issued date : November 15, 2016 FCC ID : VPYLB1KA

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)







End of Report

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone: +81 596 24 8999 Facsimile : +81 596 24 8124